

**SERVICE**



**LIST**

**EA 300/L**

EXTRA-Flugzeugbau GmbH

LBA.G.0020

Tel: +49-2858-9137-0

Schwarze Heide 21

LBA.0180

Fax: +49-2858-9137-30

D-46569 HÜNEXE

Germany

Manufacturer:	Type:	Serial Number:	Callsign:	TC:	Date:	Total Time:	Last Annual:
EXTRA	EA 300/L	1191	N269SG	A67EU/Rv. 10	22-Dec-10	152.10	10.15.2010
Part/assy	Manufacturer:	PN:	SN:	Action:	TBO:	Due-date	Due-hours
Airframe	Extra	EA 300/L	1191	Sign.It. Insp.	25 hr.		177.10
Airframe	Extra	EA 300/L	1191	Sign.It. Insp.	50 hr.		202.10
Airframe	Extra	EA 300/L	1191	Sign.It. Insp.	100 hr.		252.10
Airframe	Extra	EA 300/L	1191	Sign.It. Insp.	1000 h		1000.00
Comp. structure	Extra	EA 300/L	1191	Major Insp.	6000 h	N/A	6000.00
Engine	Lycoming	AEIO-540-L1B5	L-29695-48a	Overhaul	1400 h /12 Y.	11-Mar-17	1400.00
Propeller	Mühlbauer	MTV 9-BC/C-200-15	04375	Overhaul	1800 h/6 Y.	11-Mar-11	1800.00
Magneto LH	Slick	6351	04051677	Inspection	500 h	N/A	500.00
Magneto RH	Slick	6350	04051165	Inspection	500 h	N/A	500.00
Mech. Fuelpump	Lear Siegler	RG 9080 J4A	E2756	Overhaul	With Engine	N/A	1400.00
Elec. Fuelpump	Weldon Tool	8120-M	110925	Overhaul	With Engine	N/A	1400.00
Fuel Injector	Bendix	RSA 10 AD 1	70313405	Overhaul	With Engine	N/A	1400.00
Fuel Selector	RC Allen	6S122	9179	Inspection	On Cond.	On Cond.	On Cond.
Engine Starter	Skytec	149-12LS	F2L-240413	Overhaul	With Engine	N/A	1400.00
Alternator	Bosch	120489935	15.11.02	Overhaul	With Engine	N/A	1400.00
Battery	Concorde	RG 25 XC	CBC-40043580	Replace	24 mo.	6-Mar-05	N/A
Ignition Switch	TCM	10-357200-1	No SN	Replace	On Cond.	On Cond.	On Cond.
Exhaust System	Gomolzig	EA 300/L	188	Overhaul	On Cond.	N/A	On Cond.
Inv. Oil System	Christen	AEIO-540	No SN	Inspection	300 h	N/A	300 h
Oil cooler Front	Stewart warner	8406R	10100	Flushing	500 h	N/A	500 h
Oil cooler Rear	Stewart warner	8406R	10134	Flushing	500 h	N/A	500 h
Shock Mounts	Barry	94016-02	No SN	Replace	On Cond.	On Cond.	On Cond.
Engine Mount	Extra	EA 300	No SN	Replace	On Cond.	On Cond.	On Cond.
Engine Hoses	Superflexit	EA 300	No SN	Replace	7Y.,then 5Y.	11-Mar-12	N/A
Airframe Hoses	Superflexit	EA 300	No SN	Replace	7Y.,then 5Y.	11-Mar-12	N/A
Airframe Hoses	Knapp	EA 300	No SN	Replace	7Y.,then 5Y.	11-Mar-12	N/A
Lyc. 400h Insp.	Lycoming	Op. Manual 60297-21	No SN	Inspection	400 h	N/A	400 h
Lyc. SB 388 Insp	Lycoming	Op. Manual 60297-21	No SN	Inspection	400 h	N/A	400 h
Lyc. 12 Y. Insp.	Lycoming	Lyc. Service Letter	No SN	Inspection	12 Y.	11-Mar-17	N/A
Engine Controls	Extra	Prop, Mixer, Throttle	No SN	Replace	On Cond.	On Cond.	On Cond.
Rudder Cables	Extra	Rudder Controls	No SN	Replace	On Cond.	On Cond.	On Cond.
Rudder Fairleads	Extra	Rudder Controls	No SN	Replace	On Cond.	On Cond.	On Cond.
Control Bearings	Extra	Airframe	No SN	Replace	On Cond.	On Cond.	On Cond.
Pedal Actuators	SKF	CARR 22x20x1	No SN	Replace	On Cond.	On Cond.	On Cond.
Brake system	Cleveland	199-197	No SN	Inspection	500 h	N/A	500 h
Brake Cylinder	Matco	MC- 4E	No SN	Replace	On Cond.	N/A	On Cond.
Harness, Front	Hooker	1011230, St. Ratchet	07.07.04	Replace	6 Y.	11-Mar-11	N/A
Harness, Rear	Hooker	1011230, St. Ratchet	07.07.04	Replace	6 Y.	11-Mar-11	N/A
Smoke Fill Pump	Jabsco	Mini Puppy 12V-6A	No SN	Replace	On Cond.	On Cond.	N/A
Smoke Pump	Jabsco	Mini Puppy 12V-6A	No SN	Replace	On Cond.	On Cond.	N/A
Weight & Balanc	Extra		No SN	Weighing	5 Y.	11-Mar-11	N/A
Avionic Check	Tpx Cert	Assy	No SN	Inspection	2 Y.	4-Jun-11	N/A
Panel Mounts	Hengstenberg	5219059	No SN	Replace	On Cond.	On Cond.	On Cond.
ELT Battery	ACK	E-01	No SN	Replace	On Batt Label	1-Mar-15	N/A
ELT RCPI Batter	ACK	E-01	No SN	Replace	On Batt Label	1-Mar-17	N/A
<b>Maint. Shop:</b> SEAS - Extra Dept.		<b>Sign. Inspector</b> 	<b>Stamp:</b> 3040442	<b>Name:</b> C.Bonner	<b>Date:</b> 10.28.10		