







AIRFRAME

Company
 Manufacturer EXTRA FLUGZEUGBAU
 Model EA-300/L
 Serial # 1191
 A/C Cert. Date

Tach Time 152.1
 Total Time 152.1

Tail Number N269SG

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
98-09-10 06/07/98	NICOPRESS SLEEVES/	15 Oct 2010	C/W By inspection per SB 300-1-93	X			D.Vayda 26940361A 
*98-24-07 12/28/98	RUDDER PEDAL FOOTREST/	15 Oct 2010	N/A by S/N		X		D.Vayda 26940361A 
03-17-02 10/10/03	FUEL SELECTOR VALVE/	15 Oct 2010	C/W by inspection and leak check in accordance with the SB300-9-02= No Defects Found=, No further action required.	X			D.Vayda 26940361A 
*05-11-07 07/18/05	BOTTOM FUSELAGE COVER TO FIREWALL SEAL/	15 Oct 2010	C/W in accordance with SB 300-4-04 Bottom fuselage cover/firewall sealing.		X	Next Belly Removal	D.Vayda 26940361A 
07-02-11 02/28/07	HORIZONTAL STABILIZER ATTACHMENT/	15 Oct 2010	N/A by S/N	X			D.Vayda 26940361A 
*10-04-11 03/30/10	TAIL SPRING SUPPORT/	15 Oct 2010 TT: 152.1	Complied with by Inspection in accordance with SB 300-2-97C. No Defects found. Next inspection is due in 50hrs.		X	202.1	D.Vayda 26940361A 

ENGINE – Front

Company
 Manufacturer TEXTRON LYCOMING
 Model AEIO-540 L1B5
 Location Front
 Serial # L-29695-48a
 TSMOH
 Total Time 152.1

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
*03-14-03 08/14/03	ROTARY FUEL PUMP RELIEF VALVE SCREWS/	15 Oct 2010	Inspected the pump data plate, found to be marked "M" at the end of the Part No. This indicates compliance with Textron Lycoming Service Bulletin No. 539A considered terminating action at this time.		X		D.Vayda 26940361A
04-05-24 03/30/04	CRANKSHAFT GEAR RETAINING BOLT/	15 Oct 2010	N/A the bolt was installed during original assembly after November 10, 1998	X			D.Vayda 26940361A
04-10-14 06/25/04	CORRECTED BY AD 2004-10-14 C1/	15 Oct 2010		X			D.Vayda 26940361A
*04-10-14 C1 06/25/04	CRANKSHAFT GEAR AND GEAR RETAINING BOLT/	15 Oct 2010	N/A at this time, required if engine suffers prop strike/sudden stoppage.		X		D.Vayda 26940361A
05-19-11 10/21/05	300 HORSEPOWER OR LOWER CRANKSHAFTS/	15 Oct 2010	N/a by S/N not listed in SB 566 Table 2	X			D.Vayda 26940361A
06-10-21 06/22/06	ENGINE COMPONENTS, INC. CONNECTING RODS/	15 Oct 2010	N/A by OEM equipment installed.	X			D.Vayda 26940361A
06-12-07 07/11/06	ENGINE COMPONENTS, INC. PARALLEL VALVE CYLINDER ASSEMBLIES/	15 Oct 2010	N/A by OEM equipment installed.	X			D.Vayda 26940361A
06-20-09 11/03/06	CRANKSHAFT RETIREMENT/	15 Oct 2010	N/A by S/N not listed in SB569A at this time.	X			D.Vayda 26940361A
07-04-19 R1 05/07/07	SUPERIOR AIR PARTS, INC. CAST CYLINDER ASSEMBLIES/	15 Oct 2010	N/A by OEM equipment installed.	X			D.Vayda 26940361A
*08-14-07 08/14/08	EXTERNAL FUEL INJECTION LINES/	15 Oct 2010 / TT 152.1	Inspected The Fuel Injector Fuel Lines Between The Fuel Manifold And The Fuel Injector Nozzles In Accordance With Textron Lycoming Service Bulletin No. 342E, dated May 18, 2004. No Defects Found		X	252.1	D.Vayda 26940361A
*09-26-12 02/04/10	ENGINE COMPONENTS, INC. P/N AEL65102 "TITAN" CYLINDERS/	15 Oct 2010	N/A by OEM equipment installed.		X		D.Vayda 26940361A

PROPELLER - Front

Company
Manufacturer MT PROPELLER ENTWICKLUNG
Model MTV-9-B-C/C200-15
Location Front **Blade**
Tail # N269SG **TSMOH**
Serial # 04375 **Total Time** 152.1 **Tail Number** N269SG

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
*02-23-09 12/30/02	TORX HEAD BLADE ROOT LAG SCREWS/	15 Oct 2010	N/A by S/N		X		D.Vayda 26940361A
*06-05-05 04/10/06	SUPERSEDED BY AD 2007-26-13/	15 Oct 2010			X		D.Vayda 26940361A
*07-26-13 01/31/08	BLADE LEADING EDGE EROSION SHEATHS/	15 Oct 2010	N/A by S/N		X		D.Vayda 26940361A

* indicates possible recurring inspections © 1995 - 2007 - Tdata, Inc. (Tdata.com)

Prepared by _____

Date _____

APPLIANCES

Company
Tail # N269SG

AD# Effective	Subject	Date & Hours @ Compliance	Method Of Compliance	O	R	Next Comp @ Hrs/Date	Authorized Signature & Number
00-11-51 06/07/00	SUPERSEDED BY AD 2002-13-04/	15 Oct 2010		X			D.Vayda 26940361A
02-13-04 07/12/02	MAGNETO IMPULSE COUPLING STOP PIN/	15 Oct 2010	N/A by S/N	X			D.Vayda 26940361A
*09-02-03 02/09/09	FUEL INJECTOR SERVO PLUG AND GASKET/	15 Oct 2010	N/A by date of Manufacture is before 8/22/2006		X		D.Vayda 26940361A